

TRIO AUTOPILOT SOFTWARE CHANGE LOG

Rev -

170708A – Initial release

170708B – Minor - Corrects flashing GPSS LED when INT mode is selected

170708C – Minor – Increased maximum brightness setting

170708D – Minor software change – No functionality changes

170708E – Minor software change – No functionality changes

170708F - Minor software change – No functionality changes

170708G – Minor - Maintenance mode entry and activation improvement

170708H – Minor - Improve GPSS performance

170708J – Minor software change – No functionality changes

170708K – Minor – “Trim Up” “Trim Down” message display time limit

170708L – Minor - Not Released

170708M – Minor software change – No functionality changes

170708N – Minor software change – No functionality changes

170708P – Minor - Enables circle last waypoint when GPSS is enabled. Disables circle last waypoint when approach is active.

170708Q – Minor software change – No functionality changes

220322E - Major software change – Initial release of software to enable airdata labels from Aspen EFD 1000 and Garmin G5.

220322F – Minor software change – No functionality changes

220322G – Minor – Corrected altitude capture function, corrected intermittent “No GPS” messages, corrected lateral tracking anomalies found in 220322E and 220322F.